

InspecVision Report

Filepath: 2D Demo Part.plr
Customer: The Engineering Company
Operator: Planar User
Inspection Date: 07/06/2011 (16:24:50)
Works Order No: 123
Customer Order No: 321
Part No: 456
Customer Part No: 654
Measurement Count: 11814
Passed Count: 11732
Failed Count: 82
Report Summary: Items Passed: 32 Items Failed: 1 Items Missing: 1
Part Thickness: Nominal: 2 Actual: 2 Deviation: 0

