


Sample Report

Filepath: 2D Demo Part.plr
Customer: Inspecvision
Operator: Chris Johnston
Inspection Date: 07/06/2011 (16:24:50)
Works Order No: 001
Customer Order No: 001
Part No: 001A
Customer Part No: 001
Report Summary: Items Passed: 10
Part Thickness: Nominal: 2

Items Failed: 0
Actual: 2



Items Missing: 0
Deviation: 0



Sample Report

Customer: Inspection
 Operator: Chris Johnston
 Inspection Date: 07/06/2011 (16:24:50)
 Works Order No: 001
 Customer Order No: 001
 Part No: 001A
 Customer Part No: 001
 Report Summary: Items Passed: 10 Items Failed: 0 Items Missing: 0
 Part Thickness: Nominal: 2.000000 Actual: 2.000000 Deviation: 0.000000



Name	Entity	Datum	Dimension	Nominal	Actual	Deviation	Standard Deviation	Tolerance	Status
A	Line	Line	DistX	250	250.299	0.299	0.035	+/-0.5	Pass
B	Circle	Circle	DistX	226	226.211	0.211	0.037	+/-0.5	Pass
C	Line	Line	DistX	156	156.109	0.109	0.019	+/-0.5	Pass
D	Line	Line	DistX	55	55.076	0.076	0.028	+/-0.3	Pass
E	Line	Line	DistY	293.003	293.358	0.355	0.024	+/-0.5	Pass
F	Line	Line	DistY	160	160.15	0.15	0.026	+/-0.5	Pass
G	Line	Line	DistY	55	54.994	-0.006	0.036	+/-0.3	Pass
H	Line	Line	Degrees	45	45.178	0.178	0.019	+1/-1	Pass
I	Circle	Circle	Radius	4.5	4.519	0.019	0.035	+/-0.1	Pass
J	Circle	Circle	Radius	4.5	4.526	0.026	0.023	+/-0.1	Pass