

Boiler Plate Report



Filepath: 2D Demo Part.plr
Customer: Mi Customer Industries
Operator: Admin
Inspection Date: 29/11/2016 (10:25:37)
Works Order No: WON-asdf74
Customer Order No: CoNo-1588-a52
Part No: Pn-akk3-4f
Customer Part No: CPN-5480SASD5
Pass/Fail: Fail

Report Summary: Items Passed: 28 Items Failed: 5 Items Missing: 0 Extra Holes: 0
Part Thickness: Nominal: 2 Measured: 2 Deviation: 0

